



K27 Bristenstrasse

Data and facts

Company	PORR Equipment Services Deutschland GmbH
---------	--

Type	Rock technology
------	-----------------

Runtime	03.2017 - 10.2017
---------	-------------------

Principal	Canton Uri, Office of Civil Engineering
-----------	---

[Project report online](#)

www.porr-group.com



Emergency restoration in the mountains.

A concrete supporting wall was installed to replace the natural stone wall displaced by the moving earth. After completing some necessary blasting, the PORR team finally covered the cleared section of rock with nets. A large part of the works for this project, both on and above the rock, had to be completed by specialists on hanging ropes.

Impressions



Image notes

1

Construction in cramped terrain.

The restoration of the narrow mountain road presented enormous planning and logistical challenges for both man and machine.

2

Rapid re-connection secured.

The sole connecting road between Bristen and Amsteg was rendered impassable by the landslide in March 2017.

3

Precision with urgency.

After the landslide, time was of the essence. Even with this urgency, all works in this difficult landscape had to be completed with the highest degree of precision and care.

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG Group Communications

Absberggasse 47

1100 Wien

T +43 50 626-0

E-Mail: comms@porr-group.com